

FIRMWARE UPDATE INSTRUCTION + UPDATE HISTORY

*To assure the best possible performance of your equipment we carry out regular software updates to correct possible errors and/or adding new features. Therefore we advise you to always install the latest updates. **READ THE INTRUCTIONS + UPDATE HISTORY CAREFULLY!***

BEAMSPOT1-DMX FC

The attached "GSD-file" should be programmed using the special "FIRMWARE UPDATER2+" unit from our Briteq® brand. (order code: B05019)

Update instructions are included with the firmware updater.

UPDATE HISTORY

V1.00 (2016-09-05)

Original firmware as used in batch1.

V1.01 (2017-01-12)

We advise to install this update as it brings solutions for some known issues.

- **BUGFIX:** while used in RGBW 4CH-channel mode and lamp-behavior set to LED, the reaction time was not OK. The unwanted reaction delay was removed.

V1.02 (2019-11-22)

We advise to install this update as it brings solutions for some known issues.

- **BUGFIX:** while used in master/slave with IR-remote → only the master reacted to the blackout switch on the IP-remote, the slaves did not follow the blackout instruction.

V1.03 (2021-10-18)

IMPORTANT: This is **update is NOT NEEDED** if your machine currently runs on V1.02 firmware!

This is an update to make sure that two different processor brands can be used during manufacturing, to overcome the current global shortage of electronic components.

WWW.BRITEQ-LIGHTING.COM

©2016-2021