

FIRMWARE UPDATE INSTRUCTION + UPDATE HISTORY

*To assure the best possible performance of your equipment we carry out regular software updates to correct possible errors and/or adding new features. Therefore we advise you to always install the latest updates. **READ THE INTRUCTIONS + UPDATE HISTORY CAREFULLY!***

BT-COLORAY 60R

The attached "GSD-file" should be programmed using the special "FIRMWARE UPDATER2+" unit from our Briteq® brand. (order code: B05019)

Update instructions are included with the firmware updater.

UPDATE HISTORY

V1.00

Original firmware as used in batch1.

V1.01 (2018-08-27)

We advise to install this update as it brings solutions for some known issues.

- Solves a bug when strobing with color fade.

V1.02 (2019-10-25)

We advise to install this update as it brings solutions for some known issues.

- To avoid DMX-collision problems the projector automatically switches to DMX-mode when a DMX-signal is detected on the input, no matter which other mode was selected.

V1.03 (2021-10-19)

IMPORTANT: This is update is NOT NEEDED if your machine currently runs on V1.02 firmware.

- This is an update to make sure that two different processor brands can be used during manufacturing, to overcome the current global shortage of electronic components.

WWW.BRITEQ-LIGHTING.COM

©2019-2021