

## FIRMWARE UPDATE INSTRUCTION + UPDATE HISTORY

To assure the best possible performance of your equipment we carry out regular software updates to correct possible errors and/or adding new features. Therefore, we advise you to always install the latest updates. **READ THE INTRUCTIONS + UPDATE HISTORY CAREFULLY!**

### **BTX-SUPREME**

#### **Two update options:**

- **Using the FIRMWARE UPDATER2+:** The attached can be programmed through the DMX-input, using the special "FIRMWARE UPDATER2+" unit from our Briteq® brand. (order code: B05019) Update instructions are included with the firmware updater.  
**Attention:** the Firmware Updater2+ must have at least firmware version V1.12, otherwise the update of the BT-SHARK will not succeed.
- **Preferred option → using the USB-port:** the files can be programmed using a USB-memory stick. Please check the BTX-SUPREME user manual (section USB Update) to see how this must be done!

#### **UPDATE HISTORY**

##### **V1.1.1 (2022-05-21)**

Original firmware as used in batch1.

##### **V1.1.2 (2022-06-17)**

We advise to install this update as it brings improvements / solutions for some known issues.

- Solved: CMY only starts to fade in after DMX value 70, losing ¼ resolution

##### **V1.1.3 (2022-08-19)**

We advise to install this update as it brings improvements / solutions for some known issues.

- Solved: random delays of 2 to 3 minutes while starting the discharge lamp.

[WWW.BRITEQ-LIGHTING.COM](http://WWW.BRITEQ-LIGHTING.COM)

©2022