

FIRMWARE UPDATE INSTRUCTION + UPDATE HISTORY

*To assure the best possible performance of your equipment we carry out regular software updates to correct possible errors and/or adding new features. Therefore, we advise you to always install the latest updates. **READ THE INTRUCTIONS + UPDATE HISTORY CAREFULLY!***

EXPLORER SPOT

The attached "yfu-file" should be programmed using the special "FIRMWARE UPDATER" unit from our Briteq® brand. (order code: 4319)

Update instructions are included with the firmware updater.

UPDATE HISTORY

V06-05-05 (2023-09-13)

Original firmware as used in batch1.

V10-10-10 (2023-12-07)

We advise to install this update as it brings improvements / solutions for some known issues.

- Microphone sensitivity adjusted
(Note if not improved: on some units from batch1 the polarity of the microphone also needs to be reversed)
- Wrong spelling "CelilingHung" improved to "CeilingHung"
- Software versions of the 3 processors are renamed to V1.0

V11-10-10 (2025-08-11)

We advise to install this update as it brings improvements / solutions for some known issues.

- Bugfix: Shows (CeilingHung, etc.) now also work while used in 5MSL DMX mode.

WWW.JB-SYSTEMS.EU

©2023 - 2025