

FIRMWARE UPDATE INSTRUCTION + UPDATE HISTORY

*To assure the best possible performance of your equipment we carry out regular software updates to correct possible errors and/or adding new features. Therefore we advise you to always install the latest updates. **READ THE INTRUCTIONS + UPDATE HISTORY CAREFULLY!***

BTX-TITAN

The attached "JLY-file" should be programmed using the special "FIRMWARE UPDATER 3" unit from our Briteq® brand. (order code: 4389) – **ASK US FOR MORE INFORMATION!**
Update instructions are included with the firmware updater.

UPDATE HISTORY

V1.0 (2015-04-10)

Original firmware as used in batch1.

V1.1 (2015-07-10)

We advise to install this update as it brings solutions for some known issues.

- Improved dimmer performance.
- Filter in front of the lamp moves constantly to improve heat management
- Solves unwanted pan/tilt error warning message
- Improved Frost effect

V1.3 (2015-07-10) – used from batch 1604

We advise to install this update as it brings solutions for some known issues.

- RDM issue solved.

WWW.BRITEQ-LIGHTING.COM

©2015-2016