

FIRMWARE UPDATE INSTRUCTION + UPDATE HISTORY

*To assure the best possible performance of your equipment we carry out regular software updates to correct possible errors and/or adding new features. Therefore, we advise you to always install the latest updates. **READ THE INTRUCTIONS + UPDATE HISTORY CAREFULLY!***

BT-COLORAY MULTI

The attached "GSD-file" should be programmed using the special "FIRMWARE UPDATER2+" unit from our Briteq® brand. (order code: B05019)

Update instructions are included with the firmware updater.

UPDATE HISTORY

V1.02 (2019-06-20)

Original firmware as used in batch1.

V1.03 (2022-05-21)

IMPORTANT: This is **update is NOT NEEDED** if your machine currently runs on V1.02 firmware.

- This is an update to make sure that two different processor brands can be used during manufacturing, to overcome the current global shortage of electronic components.

WWW.BRITEQ-LIGHTING.COM

©2019-2022