

FIRMWARE UPDATE INSTRUCTION + UPDATE HISTORY

*To assure the best possible performance of your equipment we carry out regular software updates to correct possible errors and/or adding new features. Therefore, we advise you to always install the latest updates. **READ THE INTRUCTIONS + UPDATE HISTORY CAREFULLY!***

BTX-LIGHTSTRIKE

The attached firmware should be programmed using the special "FIRMWARE UPDATER" unit from our Briteq® brand. (order code: B04319)

Update instructions are included with the firmware updater.

Attention: there are 2 files so the update is done in 2 times:

- FIRST load the file starting with "BTX-LIGHTSTRIKE-V00"
- THAN load the file starting with "BTX-LIGHTSTRIKE-V**" (** is the current software version)

UPDATE HISTORY

V1.10 (2023-06-22)

This update brings new functions, improvements or solutions for some known issues.

- New DMX-modes are added → for details: see the updated user manual (attached)
- Improved dimmer behavior: much smoother dimming down to zero!

**IMPORTANT: don't mix BTX-LIGHTSTRIKE units with firmware V1.00 and V1.10 in the same setup!
Make sure that all V1.00 units are updated to V1.10, the dimmer performance is too different!**

V1.00 (2022-07-22)

Original firmware as used in batch1.

WWW.BRITEQ-LIGHTING.COM

©2022-2023