

## FIRMWARE UPDATE INSTRUCTION + UPDATE HISTORY

*To assure the best possible performance of your equipment we carry out regular software updates to correct possible errors and/or adding new features. Therefore, we advise you to always install the latest updates. **READ THE INTRUCTIONS + UPDATE HISTORY CAREFULLY!***

### **COB BLINDER 2x100W**

The attached file(s) can be programmed through the DMX-input, using the special "FIRMWARE UPDATER2+" unit from our Briteq® brand. (order code: B05019)  
Update instructions are included with the firmware updater.

#### **UPDATE HISTORY**

##### **V1.16 (2022-09-15)**

**IMPORTANT:** This is **update is NOT NEEDED** if your machine currently runs on V1.15 firmware.

This is only an update to make sure that two different processor brands can be used during manufacturing, to overcome the current global shortage of electronic components.

**Attention:** NEVER use this firmware if your unit has a serial number lower than BGL-1705

##### **V1.15 (2017-05-02)**

We advise to install this update as it brings solutions for some known issues.

Also the following functions were added or changed:

- **ADDED:** FAN SPEED (AUTO / LOW).
- **CHANGED:** LAMP BEHAVIOR (LED/HALOGEN) was changed to DIMMER SPEED where the lamp behavior can be continuously adjusted from led to halogen.

**IMPORTANT REMARK:** the ZIP-file contains 2 different files, check the serial number of the projector to see which software should be used.

- **First 4 digits of the serial number lower than BGL-1705:**  
Use the file named "COB\_BLINDER\_2x100W\_V115o.GSD"  
(display shows "V1.15o" after update)
- **First 4 digits of the serial number equal or higher than BGL-1705:**  
Use the file named "COB\_BLINDER\_2x100W\_V115.GSD"  
(display shows "V1.15" after update)

**Note:** The V1.2 user manual with these new functions can be downloaded on the product page.

[WWW.BRITEQ-LIGHTING.COM](http://WWW.BRITEQ-LIGHTING.COM)

©2017-2022