

FIRMWARE UPDATE INSTRUCTION + UPDATE HISTORY

*To assure the best possible performance of your equipment we carry out regular software updates to correct possible errors and/or adding new features. Therefore we advise you to always install the latest updates. **READ THE INTRUCTIONS + UPDATE HISTORY CAREFULLY!***

COB PAR56-100WW

The attached "GSD-file" should be programmed using the special "FIRMWARE UPDATER2" unit from our Briteq® brand. (order code: 4379)

Update instructions are included with the firmware updater.

UPDATE HISTORY

V1.02

Original software

V1.02 (2016-05)

- Improved cooling of the COB light source: cooling fan starts working at lower COB-temperature.

(Remark: by accident this software version has the same version name as the previous original one)

V1.03 (2016-08-18)

Non public update.

V1.04 (2021-03-14)

We advise to install this update as it brings solutions for some known issues.

- Modification to reduce the fan noise of the projector.
- This is an update to make sure that two different processor brands can be used during manufacturing, to overcome the current global shortage of electronic components.

WWW.BRITEQ-LIGHTING.COM

©2015-2021