

## FIRMWARE UPDATE INSTRUCTION + UPDATE HISTORY

*To assure the best possible performance of your equipment we carry out regular software updates to correct possible errors and/or adding new features. Therefore, we advise you to always install the latest updates. **READ THE INTRUCTIONS + UPDATE HISTORY CAREFULLY!***

### **LED UV-GUN 100W**

The attached "GSD-file" should be programmed using the special "FIRMWARE UPDATER2+" unit from our Briteq® brand. (order code: B05019)

Update instructions are included with the firmware updater.

#### **UPDATE HISTORY**

##### **V1.02 (2016-11-10)**

Original firmware as used in batch1.

##### **V1.04 (2018-05-14)**

Due to the use of a different opto-coupler, this software should be used on all units marked with serial numbers starting with BGL-1805 or later.

This software is backward compatible and can also be used on the previous batches (with previous opto-coupler). Updating of older units is NOT needed.

##### **V1.05 (2022-08-08)**

**IMPORTANT: This is update is NOT NEEDED if your machine currently runs on V1.04 firmware.**

- This is an update to make sure that two different processor brands can be used during manufacturing, to overcome the current global shortage of electronic components.

[WWW.BRITEQ-LIGHTING.COM](http://WWW.BRITEQ-LIGHTING.COM)

©2018 - 2022